


## Spiral Pipe Forming & Welding Line



1. Decoiling
2. Cutting
3. Transverse welding
4. Leveling
5. Trimming
6. Beveling
7. Main Drive
8. Crimping
9. Three-Roll Forming
10. Inside Welding
11. Outside Welding
12. US-Testing Pipe Body
13. US-Testing Weld Seam
14. Plasma Cutting